

UNDERCOVER .38 Special (5-shot) SPECIFICATIONS - UNDERCOVER - STAINLESS

Product Code	Caliber	Barrel Length	Finish	Grips	Overall Length	Height	Weight
73820	.38 Spl	2 in (5.1 cm)	Stainless	Checkered walnut panel	6¼ in: (15.9 cm)	454 in (10.8 cm)	18 oz. (51 kg)
73820P*	38 Spl	2 in. (2.1 cm)	Standens	Checkered walnut panel	6% in. (13.9 cm)	454 in. (10.8 cm)	18 oz. (51 kg)

Sights: Patridge type ramp front sight, square nosch mar sight.

*Pocket Hamm

PARTS & PRICES

View Na	Part Number	Part Description	Unit Price	View No.	Peri Number	Part Description	Unit:
1	PRALSH0005	2" Barrel Assembly - Complete		26	7R000309V3	Eactor Red Head	\$ 1.50
A	COMMODIA	Includes rice to, 2	*\$40.66	27.	PR000985V5	Escare Rud Return Spring	.73
20	PRESI 130/05	Front Sight only.	5.30	28.	PR000306VS	Easter Rod Washer	175
	Control of the Control	Front Sight, Installed	22.50	29	1-A39	Firing Pix	1.25
× .	PROTOGORS.	Crane	7.06	30.	PRODUSTVS.	Firing Pin Spring	1.00
4	P9.000453V3	Crane Seres	1.35	31.	FR000093V3	Firing Fir Remining For	.75
4	6-A55	Crase Score Waster	.56	100		(wad/or)-	
6	PRO100SRAS	Gelinder-includes view no. 7	*80.00	31.	#R000095V3-	Retaining Pin.	.75
7.	Paris Property les.	Eirear		32.	PR013802A8	Frame Assembly - Complete	95.00
B	PR-500000405	Cylinder Land	5.25	2.10	11111111111111	Includes view nor. 1 & 2.	
	PR0000002VS	Cylinder Lach Waster	1.00	33.	PR000097V3	France Assembly Fin	11,000
in.	PR/9000001VS	Cylinder Look Planger	1.00	-00		(aud/or)-	
11.	PERCENTALVS.	Cylinder Lank Plunger Spring	.75	31.	PRODOGOTVS -	Trigger Pir	11/00
100	PROMOSSYS	Cellader Lasch Contr. Place	1.00	54.	PRODUCTIVS:	Frame Assembly Screw	1,00
13	PROMISSEVS	Cylinder Lauch Resisting Screw		33.	PR001001A3	Gree Frame & Trigger Guard	
14	PR/9006827V3	Criteder Laub Release Score	1.00	191	S. Principle of the	Includes view po. 36	16.00
100	P#000501V3	Cylinder Sup	2.55	46.	PRINCIPIZVS	Grip Locating Fin only	.75
16.	PRESONSEQVIS	Celleder Step Bushing	.73	22.	PR001285VS	Grego Storem	1.00
17.	P90000005V8	Criteder Placager	1.00	36.	PR001298AW	Griss - Checkered Panel	10.50
100	I sensonly 1 is	(and/or!-		29.	PRO1066485	Mand.	2.25
12.	PK000005VS	Hanney Plunget	1.00	407	P9.01070105	Hanner-Regular	6.50
18-	PRIMODEAVS	Cylinder Plunger Spring	75	140	PRO107940S	ffammer - Spurlem	12.60
	Chairman.	(apd/ori-		43	PROTOBOGRS	Hammer Block	3.50
18:	PRIMODELVS	Harrener Planger Spring	.73.	43.	P9L0007920S	Hammer Pavel	2,15
19:	PR000704VS	Cylinder Stud	1.25	44.	PR/000795VS	Hammer Pavil Pin-	25
100	PRIMITION	Rectur Rod Assembly Fin	.75	45.	PR.000196VS	Hammer Screw	1.25
zi.	PEN00301V8	Easter Rod Bushing	1.00	46.	PROTEINIVE	Main Spring	1.00
15.	PRIMOSESVS	Dector Red Lock Spring	75	43.	PR.001102V5	Main Spring Golde Red	1.00
25	PR000304VS	Dectar Red	3.00	48.	P\$600180V5	Main Spring Sout	.75
24:	PR000008VS	Rector Red Collar	1.23	45.	P9000000005	Trigger	7.00
D.	PRINGSSTVS	Elector Rod Collar Spring	75	56.	P9L000682V5	Trapper Spring	.75
-		Annex due see alima		51	PR000681VS	Topper Spring Bushing	1.00

Region from equilation - part on old approach

Ordering Information
When ordering parts, specify
Model number
Serial number
View number
Part description
Minimum parts order; \$5.00

Repairs.

Charges

Gue must be returned directly to the factory of an authorized increase station (addresses below). Suppress of gue and charges for repairs or parts must be PKEPALLA COLLEGAT SHIPMENTS WILL NOT BE ACCEPTED. No. CODD. Missiones labor charges \$12.00 (unless otherwise specified by Gustemer Service Manager). Refinishing and readjusting combined: \$25.00 plus the test of any parts needing replacement.